

Tele GE-020-25818923/Fax  
Email id- ipfykirk4-mes@nic.in  
AE (QS&C)/AGE 'T' 020-25810192

Garrison Engineer (I) (P) Fy  
8, Engine House Road  
Ordnance Estate  
Kirkee, Pune - 411 003

2373/KV RHE/ 104 /E2

Kendriya Vidyalaya R.H.E  
Khadki  
Pune - 411 020

22 Sep 2019

22/9/19  
2-12

**CERTIFICATE OF SAFETY & SECURITY OF SCHOOL BUILDING**

1. Ref your letter No. F.2727/217/KV/RHE/2019-20 dated 15 Jul 2019.
2. It is intimated that the inspection regarding safety and security of school Bldg was carried out by this department on 22 Aug 2019 and the following details were observed :-
  - (a) Cracks in 04 Nos columns in the rear of Left Wing and 06 Nos columns in rear of Middle Wing have been seen to be developed which have began the corrosion of reinforcement and the same requires immediate repairs.
  - (b) The roof drops are also requiring repairs.
  - (c) Balance portion of the building is visibly safe.
3. In view of the above, it is certified that the Bldg of Kendriya Vidyalaya at Range Hills Estate, Khadki, Pune is found safe at present however repairs are required for the portions mentioned in Para 2 above.

(Yogesh Paliwal)  
Major  
Garrison Engineer

Copy to:-

AGE B/R (Fy) CQA  
Kirkee,Pune -03

श्री अंजने सर  
27/9/2019

प्राचार्य/Principal  
के.वि. रेंजहिल्स/KV RHE  
खडकी, पुणे-20/Khadki, Pune-20.